

FILE 'REGISTRY' ENTERED AT 16:58:57 ON 03 JUL 2006

L1 133 SEA ABB=ON PLU=ON CU/MF
 L2 1 SEA ABB=ON PLU=ON COPPER/CN
 L3 264 SEA ABB=ON PLU=ON CU.SI/MF
 L4 4 SEA ABB=ON PLU=ON CU SI/MF
 L5 48 SEA ABB=ON PLU=ON CU SI/ELF
 L6 82 SEA ABB=ON PLU=ON SI/MF
 L7 1 SEA ABB=ON PLU=ON SILICON/CN
 L8 82 SEA ABB=ON PLU=ON L6 OR L7

FILE 'HCAPLUS' ENTERED AT 17:01:37 ON 03 JUL 2006

L9 1254 SEA ABB=ON PLU=ON L8(L)MOA/RL AND ((L1 OR L2 OR L3 OR L4 OR
 L5) OR CUSI OR (COPPER OR CU) (5A) (SI OR SILICON))
 L10 35 SEA ABB=ON PLU=ON (SI OR SILICON) (W)DOPED(W) (CU OR COPPER)

FILE 'REGISTRY' ENTERED AT 17:03:22 ON 03 JUL 2006

L11 28602 SEA ABB=ON PLU=ON COPPER ALLOY AND CU>80/MAC
 L12 5527 SEA ABB=ON PLU=ON L11 AND (SI OR SILICON OR SI/MAC)

FILE 'HCAPLUS' ENTERED AT 17:04:10 ON 03 JUL 2006

L13 6 SEA ABB=ON PLU=ON L12(L)MOA/RL AND ((L1 OR L2 OR L3 OR L4 OR
 L5) OR CUSI OR (COPPER OR CU) (5A) (SI OR SILICON))
 L14 1749 SEA ABB=ON PLU=ON (L3 OR L4 OR L5)
 L15 119 SEA ABB=ON PLU=ON L14 AND ATOM###(A) (SI OR SILICON)
 L16 17 SEA ABB=ON PLU=ON L14 AND DOP####(A) (SI OR SILICON)
 L17 12 SEA ABB=ON PLU=ON L14 AND ADD#####(A) (SI OR SILICON)
 L18 236 SEA ABB=ON PLU=ON L14 AND (RATIO OR PROPORTION OR CONCENTRATI
 ON OR DENSITY OR AMOUNT OR PERCENT OR WT OR WEIGHT OR ATOMIC) (2
 A) (SI OR SILICON)
 L19 460 SEA ABB=ON PLU=ON L14 AND (1 OR 2 OR 3 OR 4 OR 5 OR 6 OR 7
 OR 8 OR 01 OR 0) (2A) (SI OR SILICON)
 L20 27 SEA ABB=ON PLU=ON L14 AND (XSI OR YSI OR SI1 OR SIX OR SIY
 OR SI0 OR 0SI)
 L21 1047 SEA ABB=ON PLU=ON (L1 OR L2 OR L3 OR L4 OR L5) AND L9
 L22 7 SEA ABB=ON PLU=ON L12 AND L21
 L23 0 SEA ABB=ON PLU=ON L15 AND L21
 L24 5 SEA ABB=ON PLU=ON L18 AND L21
 L25 3 SEA ABB=ON PLU=ON L19 AND L21
 L26 297 SEA ABB=ON PLU=ON (L1 OR L2) AND L14 AND L8
 L27 15 SEA ABB=ON PLU=ON L15 AND L26
 L28 32 SEA ABB=ON PLU=ON L18 AND L26
 L29 48 SEA ABB=ON PLU=ON L19 AND L26
 L30 11 SEA ABB=ON PLU=ON (L1 OR L2 OR L3 OR L4 OR L5) AND L10
 L31 169 SEA ABB=ON PLU=ON L10 OR L13 OR L16 OR L17 OR L20 OR (L22 OR
 L23 OR L24 OR L25) OR (L27 OR L28 OR L29 OR L30)
 L32 6 SEA ABB=ON PLU=ON L31 AND ?INTERCONNECT?
 L33 1 SEA ABB=ON PLU=ON L31 AND ?DAMASC?
 L34 0 SEA ABB=ON PLU=ON L31 AND INLAY?
 L35 0 SEA ABB=ON PLU=ON L31 AND INLAID?
 L36 0 SEA ABB=ON PLU=ON L31 AND SEED#####
 L37 7 SEA ABB=ON PLU=ON L32 OR L33

FILE 'STNGUIDE' ENTERED AT 17:13:17 ON 03 JUL 2006

FILE 'WPIX, JAPIO' ENTERED AT 17:15:18 ON 03 JUL 2006

L38 1 SEA ABB=ON PLU=ON US 6518184/PN
 L39 SEL PLU=ON L38 1- PRN : 1 TERM
 L40 2 SEA ABB=ON PLU=ON L39
 D MAX 1-2

FILE 'STNGUIDE' ENTERED AT 17:15:37 ON 03 JUL 2006

FILE 'HCAPLUS' ENTERED AT 17:19:56 ON 03 JUL 2006

L41 42789 SEA ABB=ON PLU=ON (PARTS OR PPM OR ATOM OR ATOMIC####) (2A) (SI
 OR SILICON)
 L42 36 SEA ABB=ON PLU=ON L31 AND L41
 L43 34 SEA ABB=ON PLU=ON L42 NOT L37
 L44 4 SEA ABB=ON PLU=ON L43 AND SEMICONDUCT#####
 L45 5 SEA ABB=ON PLU=ON L43 AND DEVICE
 L46 6 SEA ABB=ON PLU=ON L44 OR L45